



Sauter GmbH

Ziegelei 1
D-72336 Balingen
E-Mail: info@sauter.eu

Tel: +49-[0]7433-9933-199
Fax: +49-[0]7433-9933-149
Internet: www.sauter.eu

Instruction Manual Ultrasonic Material Thickness Gauge

SAUTER TD-US

Version 1.2
09/2017
GB

Importør:
Impex Produkter AS
Gamle Drammensvei 107
1363 Høvik
www.impex.no
info@impex.no
Tel.: 22 32 77 20



PROFESSIONAL MEASURING

TD_US-BA-e-1712



SAUTER TD-US

Version 1.2 09/2017

Instruction Manual

Ultrasonic Material Thickness Gauge

Thank you for buying a SAUTER digital Ultrasonic Thickness Gauge. We hope you are pleased with your high quality Thickness Gauge with its big functional range. If you have any queries, wishes or helpful suggestions, do not hesitate to call our service number.

Summarize:

1	Features.....	3
2	Specifications	3
3	Front panel description	4
4	Material selection.....	4
5	Calibration	5
6	Measuring procedure	5
7	Measuring by velocity setting.....	6
8	Battery replacement	6

Annotation: It is strongly recommended to calibrate the new instrument before the first use, as described in paragraph 5. By doing this it will be achieved a much better measurement result right from the start.

1 Features

- * The exclusive Micro- computer LSI offers high measurement accuracy.
- * The instrument offers high power of emission and a wide spectrum of receiving sensitivity.
- * Sensors of different frequencies can be identified.
- * Rough surfaces, even cast iron, can be measured.
- * It is used in almost all kinds of industries.
- * Convenient to measure the thickness of many materials, e.g. steel, cast iron, aluminium, red copper, brass, zinc, quartz glass, Polyethylene, PVC, grey cast iron, nodular cast iron.
- * Automatic power-off to preserve batteries.
- * Data transfer to PC possible. Cable and software can be obtained as optional accessory.

2 Specifications

Display: 4 digits, 10mm LCD

Range: 1.2-225mm (45# steel)

Resolution: 0.1mm / 0.001 inch

Accuracy: $\pm (0.5\%n+0.1)$

Sound velocity: 500 to 9000m/s

Power supply: 4x1.5V AAA (UM-4) battery

Operating conditions: Temperature: 0 to 50°C

Humidity: <80%

Dimensions: 120 x 62 x 30mm (4.7 x 2.4 x 1.2 inch)

Weight: about 164g (batteries not included)

Accessories: Carrying case
Instruction manual
Ultrasonic sensor

3 Front panel description



- 3- 1 Sensor plug
- 3- 2 Display
- 3- 3 mm/ inch key
- 3- 4 Power- key
- 3- 5 Material selection key
- 3- 6 Plus- key
- 3- 7 Ultrasonic sensor
- 3- 8 Calibration key
- 3- 9 Minus- key
- 3-10 Battery compartment/ cover
- 3-11 Coupling indicator
- 3-12 Base plate
- 3-13 Ultrasound velocity key
- 3-14 RS-232C interface

4 Material selection

4a) The instrument has to be switched on by the Power- key 3-4.

4b) Selection of the material to be tested has to be done by pressing the material selection key. Code `cdxx` or `xxxx` will be displayed.

`cd` is the abbreviation for `code` and `xx` is a number among 0.1 and 11 that stands for the material to be measured as shown in the scale below.

`.xxxx` is a 4-digit number, displaying the sound velocity of the material which has been defined by the user.

The `cdxx` material relationship is as follows:

Nr.	Code	Material
1	cd01	Steel
2	cd02	Cast iron
3	cd03	Aluminium
4	cd04	Red copper
5	cd05	Brass
6	cd06	Zinc
7	cd07	Quartz glass
8	cd08	Polyethylene
9	cd09	PVC
10	cd10	Grey cast iron
11	cd11	Nodular cast iron
12	xxxx	Sound velocity

4c) The Plus key 3-6 or the Minus key 3-9 has to be pressed to select the material code to measure. Then the material selection key 3-5 has to be pressed to confirm. The instrument changes into the measuring mode and on the display occurs `0`.

If a material code is selected without confirming this selection, the instrument will automatically change back into the measuring mode after a few seconds.
In this case the primary material code will still be stored before switching off.

4d) A 4-digit number will be shown on the display by pressing the Plus key 3-6 when displaying `cd11` or the Minus key 3-9 has to be pressed when displaying `cd01`.
The 4-digit number is the last sound velocity being defined by the user. By changing velocity, varying qualities of materials can be compensated.

4e) If the material code has once been selected and saved, it is stored in the memory of the instrument. As long as no modification is done, the instrument will always raise (use) this material code.

4f) To get into the menu selection of the material code, the Material selection key 3-5 has to be pressed. To quit the menu, material selection key has to be pressed again or it has to be waited until the instrument- after a few seconds- changes back into Measurement mode. On the display appears `0`.

5 Calibration

5a) 5.1 A little bit gel has to be dropped onto the base plate 3-12.

5b) The calibration key 3-8 has to be pressed and `CAL` appears on the display.
`CAL` is the abbreviation for calibration.

5c) The sensor 3-7 has to be pressed slightly on the base plate. The coupling symbol **((•))** (measurement in action) occurs, if the measuring procedure has been established successfully by the process of ultrasound sending and receiving.
On the display appears `5.0mm` or 0.197 inch (debit thickness of the base plate) and `CAL` in turn.

As soon as the value is stabilized, the `CAL` key 3-8 has to be pressed to confirm.
Then the instrument changes back to the measuring mode.

5d) Like this, calibration has been finished and automatically saved in the instrument.

6 Measuring procedure

6a) The Power key 3-4 has to be pressed to switch on the instrument.

6b) The mm/ Inch key 3-3 has to be pressed to select the correct measurement unit.

6c) The sensor 3-7 has to be placed onto the material surface to be measured, provided that the material code has been selected correctly.
Assure yourself that coupling is fine and the symbol **((•))** 3-11 is active. The measurement result is to be shown on the display.

6d) The measurement result is saved until a new measurement is performed. The last value is conserved in the display until the instrument is switched off.

6e) The instrument can be switched off by either by the Power- on/ Power- off key or by Auto Power off function, one minute after the last key operation.

7 Measuring by velocity setting

7a) By pressing the VEL- key 3-13, the last saved ultrasound velocity is displayed.

7b) Measuring of coatings & materials by a known thickness:

Ultrasound velocity can be adjusted by pressing the Plus- or the Minus- key. By doing this, the value shown in the display is changed higher or lower. First the increase is 10m/ s. If the Plus- or Minus- key is pressed for longer than 4 seconds, the increase is 100m/ s.

7c) A little bit gel has to be dropped onto the material to be measured. Now the sensor 3-7 is pressed onto the surface to be measured. The reading on the display is the thickness, assumed that coupling is well.

If velocity of a special material is known, it is easy to measure the thickness with the help of step 7b).

7d) Measuring of coatings & materials with an unknown thickness:

A test material of known thickness has to be selected.

Step 7.b) (velocity setting) and 7.c) has to be repeated until the measured value is exactly the same as the known thickness. In this case the set value is the velocity of the material to be measured. With this, any number of unknown thicknesses of the same material can now be measured.

7e) To change velocity, VEL- key 3-13 has to be pressed.

To return into the measuring mode, this key has to be pressed again or it has to be waited until the instrument automatically shows `0`.

7f) By using velocity measurement, the coating thickness or the thickness of any hard And homogenous materials can easily be measured.

8 Battery replacement

a) If the battery symbol appears on the display, batteries have to be replaced.

b) The battery cover has to be removed from the instrument and the batteries have to be taken off.

c) Batteries have to be installed, paying carefully attention to polarity.

d) If the instrument is not used for a longer period, batteries should be removed.

Annotation:

To have a look at the CE Declaration of Conformity, please click onto the following link: <https://www.kern-sohn.com/shop/de/DOWNLOADS/>