

## Digital torquemeter SAUTER DA











# Comfortable testing of screw tops, e.g. bottles, jars

## **Features**

- II Optimised for torque testing of bottles, jars and other packaging with screw tops with a maximum diameter of 160 mm, e.g. in the food industry and pharmaceutical industry, as well as in the manufacturing of cosmetics such as, for example, lipsticks, etc.
- 2 Quick pin system: The four bottle mounts (holders) are pushed in, instead of being screwed in, to save time. This allows you to reconfigure quickly for other bottle sizes
- · Metal housing for continuous use in tough environmental conditions
- 3 Capacity display: A bar lights up to show how much of the measuring range is still available.
- 3 LCD graphics display with backlight
- · Rubber feet with anti-slip feature

- · Scope of delivery: four bottle mounts with rubber coat, sturdy carrying case
- Internal data memory saves up to 500 measurements. The memory contents can be transferred to the PC using optional software
- 4 USB and RS-232 data interfaces included
- Peak hold function to capture the peak value or Track function for continuous display of measurement
- · Can be used in both directions of rotation
- · Measuring with tolerance range (limit-setting function): Upper and lower limiting can be programmed individually. The process is supported by an audible and visual signal
- · AUTO-OFF function

## Technical data

- Selectable units: Nm, lbf-in, kgf-cm, kgf-m, ft-lbf
- Precision: ± 0,5 % of [Max]
- Measuring frequency: 1000 Hz
- · Usable measuring range: 5-100 % of [Max]
- · Overload protection: 150 % of [Max]
- · Rechargeable battery pack integrated, standard, operating time up to 18 h without backlight, charging time approx. 14 h
- Overall dimensions W×D×H 250×160×100 mm
- · Net weight approx. 3 kg

## **Accessories**

- Plug-In for data transfer of measuring data from the measuring instrument and transfer to a PC, e.g. in Microsoft Excel®, SAUTER AFI-1.0
- · Force-time data transfer software for graphical representation on the PC and data transfer to Microsoft Excel®, SAUTER AFH FAST
- · RS-232/PC connection cable SAUTER FL-A04
- · USB/PC connection cable SAUTER FL-A01

STANDARD

























Model	Measuring range	Readout	Diameter test object		Option  Factory calibration certificate	
	[Max]	[d]				
SAUTER	Nm	Nm	mm		KERN	
DA 1-4	1	0,0002	10-165		961-120	
DA 5-3	5	0,001	10-165	•	961-120	
DA 10-3	10	0,002	10-165	0	961-120	



## **Pictograms**



#### Adjusting program (CAL):

For quick setting of the instrument's accuracy. External adjusting weight required.



#### Calibration block:

standard for adjusting or correcting the measuring device.



## Peak hold function:

capturing a peak value within a measuring process.



#### Scan mode:

continuous capture and display of measurements



## Push and Pull:

the measuring device can capture tension and compression forces.



### Length measurement:

captures the geometric dimensions of a test object or the movement during a test process.



#### Focus function:

increases the measuring accuracy of a device within a defined measuring range.



## Internal memory:

to save measurements in the device memory.



### Data interface RS-232:

bidirectional, for connection of printer and PC.



# Data interface USB:

To connect the measuring instrument to a printer, PC or other peripheral devices.



#### Data interface Infrared:

To transfer data from the measuring instrument to a printer, PC or other peripheral devices.



#### Control outputs (optocoupler, digital I/O):

to connect relays, signal lamps, valves, etc.



## Analogue interface:

to connect a suitable peripheral device for analogue processing of the measurements



#### Statistics

using the saved values, the device calculates statistical data, such as average value, standard deviation etc.



#### PC Software:

to transfer the measurement data from the device to a PC.



#### Printer:

a printer can be connected to the device to print out the measurement data.



#### GLP/ISO record keeping:

of measurement data with date, time and serial number. Only with SAUTER printers



#### Measuring units:

Weighing units can be switched to e.g. non-metric at the touch of a key. Please refer to website for more details.



# Measuring with tolerance range (limit-setting function):

Upper and lower limiting can be programmed individually. The process is supported by an audible or visual signal, see the relevant model



ZERO

#### ZERO:

Resets the display to "0".



#### **Battery operation:**

Ready for battery operation. The battery type is specified for each device.



#### Rechargeable battery pack:

rechargeable set.



#### Mains adapter:

230V/50Hz in standard version for EU. On request GB, AUS or USA version available.



#### Power supply:

Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or USA on request.



#### Motorised drive:

The mechanical movement is carried out by a electric motor.



#### Motorised drive:

The mechanical movement is carried out by a synchronous motor (stepper).



#### Fast-Move:

the total length of travel can be covered by a single lever movement.



#### DAkkS calibration possible:

The time required for DAkkS calibration is shown in days in the pictogram.



#### Factory calibration:

The time required for factory calibration is specified in the pictogram.



#### Package shipment:

The time required for internal shipping preparations is shown in days in the pictogram.



#### Pallet shipment:

The time required for internal shipping preparations is shown in days in the pictogram.

# Your KERN specialist dealer:

Impex Produkter AS Gamle Drammensvei 107 1363 Høvik www.impex.no info@impex.no Tel.: 22 32 77 20